



State of Utah

Department of **Natural Resources**

MICHAEL R. STYLER Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA Division Director JON M. HUNTSMAN, JR. Governor

GARY R. HERBERT Lieutenant Governor

Representativ	es Present During the Inspection:		
Company	Vicky S. Miller Environmental Specialist		
OGM	Pete Hess Environmental Scientist III		

Inspection Report

Permit Number:	C0070039			
Inspection Type:	PARTIAL			
Inspection Date:	Monday, November 20, 2006			
Start Date/Time:	11/20/2006 10:20:00 AM			
End Date/Time:	11/20/2006 2:30:00 PM			
Last Inspection:	Tuesday, October 31, 2006			

Inspector: Pete Hess, Environmental Scientist III

Weather: Clear, warm; 40's F. InspectionID Report Number: 1142

Accepted by: whedberg

11/28/2006

Permitee: CANYON FUEL COMPANY LLC Operator: CANYON FUEL COMPANY LLC

Site: DUGOUT CANYON MINE

Address: PO BOX 1029, WELLINGTON UT 84542

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages

9,471.00	Total Permitted			
57.75	Total Disturbed			
	Phase I			
	Phase II			
	Phase III			

Mineral Ownership

Types of Operations ✓ Federal ✓ Underground ✓ State Surface County Loadout Processing Other Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

The Permittee is current relative to the submittal of surface and ground water monitoring information to the Division electronic data base. The Special Permit Condition which is included in Attachment "A" the current State permit is being met.

There are no pending compliance actions for the Dugout Canyon Mine permit area.

Inspector's Signature:

Pete Hess, Environmental Scientist III

Inspector ID Number: 46

Monday, November 20, 2006 Date

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Permit Number: C0070039 Inspection Type: PARTIAL

Inspection Date: Monday, November 20, 2006

Page 2 of 4

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcemen
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers	V			
3.	Topsoil	✓			
4.a	Hydrologic Balance: Diversions	V			
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	V		✓	
4.c	Hydrologic Balance: Other Sediment Control Measures	✓		✓	
4.d	Hydrologic Balance: Water Monitoring	✓		✓	
4.e	Hydrologic Balance: Effluent Limitations	✓		✓	
5.	Explosives	✓			
6.	Disposal of Excess Spoil, Fills, Benches		✓		
7.	Coal Mine Waste, Refuse Piles, Impoundments	V		✓	
8.	Noncoal Waste	V			
9.	Protection of Fish, Wildlife and Related Environmental Issues	V			
10.	Slides and Other Damage	V		✓	
11.	Contemporaneous Reclamation	V		V	
12.	Backfilling And Grading		V		
13.	Revegetation	V			
14.	Subsidence Control	V		V	
15.	Cessation of Operations		V		
16.a	a Roads: Construction, Maintenance, Surfacing	V		V	
16.Ł	Roads: Drainage Controls	✓			
17.	Other Transportation Facilities	✓			
18.	Support Facilities, Utility Installations	✓		✓	
19.	AVS Check	✓			
20.	Air Quality Permit	✓			
21.	Bonding and Insurance	✓			
22.	Other				

Permit Number: C0070039
Inspection Type: PARTIAL

Inspection Date: Monday, November 20, 2006

Page 3 of 4

4.b Hydrologic Balance: Sediment Ponds and Impoundments

The Permittee provided the Division with copies of the third and fourth quarter impoundment inspections for the two impoundments associated with the Pace Canyon fan portal facility. A UPDES permitted catch basin treats disturbed area runoff, prior to it entering Pace Creek. A small basin at the toe of the soil storage pile on the north end of the Pace Canyon facility treats any runoff reporting to it via total containment. There were no compliance issues noted relative to either of these impoundments this day..

4.c Hydrologic Balance: Other Sediment Control Measures

The silt fences which were inspected this day appeared capable of functioning as designed.

4.d Hydrologic Balance: Water Monitoring

Pace Creek was flowing beneath its frozen surface. The elevation of the water in the Mine site pond was approximately thirty inches below the primary discharge elevation.

4.e Hydrologic Balance: Effluent Limitations

Ms. Miller discussed the possibility of using salt on the waste rock site access road for safety reasons. The Division suggested that the Permittee contact Mr. Jeff Studenka relative to the storm water permit which is in place at this site. It is believed that salt storage and usage would be covered under the permitting of that document.

7. Coal Mine Waste, Refuse Piles, Impoundments

The Permittee has received a conditional approval for an expansion of the refuse pile facility, (Task ID #2550). The expansion will increase the available waste storage acreage from 5.7 acres to 12.25 acres. The Permittee has found it necessary to move the gate required by 30 CFR 77.214(d). The new location is further inby, allowing a flat area where truck operators can set their brakes and exit the vehicle to gain access. The disturbed area perimeter fence remains unchanged.

10. Slides and Other Damage

A failure of the sandstone escarpment immediately northwest of the Pace Canyon air shaft damaged the security fence and the Hilfiker wall as it rolled down the slope. A boulder landed close to the fan duct housing over the shaft; no damage occurred to the fan. The Division does not see a need to remove this boulder. Several smaller boulders also exist. The Permittee has hired a contractor to repair the fence.

11. Contemporaneous Reclamation

The Permittee's contractor has roughened the access road to degasification well G-3. Seeding of this area is on the "To Do" list.

Inspection Continuation Sheet

Permit Number: C0070039 Inspection Type: PARTIAL

Inspection Date: Monday, November 20, 2006

Page 4 of 4

14. Subsidence Control

The Permittee has completed the repair of the subsidence cracks associated with degasification well G-7.

16.a Roads: Construction, Maintenance, Surfacing

The Permittee's contractor (Nielson Construction) has completed the new grade requirements for the waste rock site access road (permitted via Task ID #2577). The travel width has been black topped.

18. Support Facilities, Utility Installations

The Permittee's drilling contractor has completed the degasification well bore designated as G-9B. Ms. Miller indicated that the drillers would be off of the Roan Cliffs by November 21, 2006.